



REBUILT LIKE NEW!

Fuji TN-40



Built: 2003 Serial# 15757 Control: 21i-TB A2-8 Spindle

Price: \$ 115,000

List of repairs/new components

1. Spindle Motor rebuilt
2. Rebuilt turret
3. New lube blocks
4. Flush lube lines, replaced where needed
5. New Ballscrews and bearings for X and Z Axis
6. Saddle rescraped and new fitted gibs
7. Wipers/scrapers
8. Completely cleaned and painted

Note: Chipconveyor included.

Contact Us: 423-887-5656; 865-388-6580 info@precision-tec.com

www.Precision-Tec.com